


Index No. J 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 13 Corner common to sections 12, 13, AND 7, 18-139-27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees	Distance
<u>W. PINE</u>	<u>W. PINE</u>	<u>W. PINE</u>	<u>W. PINE</u>
<u>24"</u>	<u>20"</u>	<u>22"</u>	<u>24"</u>
<u>N58E</u>	<u>S38E</u>	<u>S9W</u>	<u>N75W</u>
<u>5 LKS.</u>	<u>40 LKS</u>	<u>47 LKS</u>	<u>34 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK  
Location filed COUNTY RESURVEY "E-8, E-10"  
Monument  
1919, BEN CLARK, COUNTY BOOK "C" P. 307 SET 4x36" POPLAR  
POST 119.7' EAST OF CENTER OF RAILROAD TRACK.  
1919, BEN CLARK, BOOK "C" P. 314 SET 3x30" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC  
Washburn Lake - BK#2 P. 3  
Start east from I.P. marked: 12/7  
also 3" S.E. cedar w/ tag 13/18  
1936 - BK# 7, P. 24 start south from 2 1/2" I.P.  
1938 - BK# 13 P. 13 - start west from corner.  
BK# 20 - corner 81' east of control post on old grade  
Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>POPLAR</u>	<u>6"</u>	<u>N50W</u>	<u>33.8'</u>
<u>POPLAR</u>	<u>7"</u>	<u>S34W</u>	<u>42.7'</u>
<u>W. PINE STUMP</u>	<u>24"</u>	<u>S62-30</u>	<u>6'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_