


Index No. 53

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5th Coordinates: X _____ Y _____
N 1/4 18 Corner common to sections 7, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species BIRCH BIRCH _____
Diameter 7" 6" _____
Bearing N10W S40E _____
Distance 15 Lks. 30 Lks. _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK
Location filed COUNTY RESURVEY "E-9, E-11"
Monument IRON MONUMENT
1919, BEN CLARK, COUNTY BOOK "C" P. 331 F.V.D. L.P.

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC
Washburn Lake - BK #12 P. 23
at 2640' from E - set approx 1/4 cc.

Bearing Trees, Reference Objects

Species J. PINE _____
Diameter 5" _____
Bearing S40E _____
Distance 29.7' _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____