


Index No. N 11

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 21 Corner common to sections 16, 21



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species ASPEN ASPEN \_\_\_\_\_  
Diameter 7" 7" \_\_\_\_\_  
Bearing N 28 E S 42 E \_\_\_\_\_  
Distance 3 LKS 7 LKS. \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK  
Location filed COUNTY RESURVEY "E-10"  
Monument IRON MONUMENT  
1919, BEN CLARK, COUNTY BOOK "C" P. 322 Fwd Hub.  
P. 323 I.P.

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC  
Washburn Lake - BK # 12 P. 19  
at 2687' from W. fence South

Bearing Trees, Reference Objects

Species W. OAK \_\_\_\_\_  
Diameter 12" \_\_\_\_\_  
Bearing N 42 W \_\_\_\_\_  
Distance 64 2' \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_