

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_

Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed:

Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed:

Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed:

Monument:

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed:


Monument:

Index No. N 13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

NE 21 Corner common to sections 15, 16, 21, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees		
<u>J. PINE</u>		<u>TAM.</u>	<u>W. PINE</u>	<u>J. PINE</u>
<u>8"</u>		<u>5"</u>	<u>9"</u>	<u>8"</u>
<u>N10E</u>		<u>NRTW</u>	<u>S68E</u>	<u>S42W</u>
<u>275 LKS</u>		<u>113 LKS</u>	<u>132 LKS</u>	<u>250 LKS</u>

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK  
Location filed COUNTY RESURVEY "E-10"  
Monument IRON MONUMENT  
1919, BEN CLARK, COUNTY BOOK "C" P. 335 END NE SE, AND SW BOTS SET 3x30" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCC  
Wash burn Lake - BK # 12 P. 18.  
End 2" IIP w/cap 5283' from E.  
BK 12 P. 20 at 5280' from W. offset 280' N TO  
2" IIP w/cap End w/line 22" N10 1/2 W 234' ?

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. PINE</u>	_____	_____
<u>22"</u>	_____	_____
<u>N10W</u>	_____	_____
<u>31.2'</u>	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_