


Index No. N17

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 22 Corner common to sections 14, 15, 22, 23



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>W. PINE</u>	<u>W. BIRCH</u>	<u>W. PINE</u>
Diameter	<u>6"</u>	<u>7"</u>	<u>6"</u>
Bearing	<u>N 55 E</u>	<u>N 65 W</u>	<u>S 30 W</u>
Distance	<u>51 LKS.</u>	<u>18 LKS</u>	<u>60 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK
Location filed COUNTY RESURVEY "E-10"
Monument IRON MONUMENT
1919, BEN CLARK, COUNTY BOOK "C" P. 335 SET 3X30"
I.P. W/ FND W. PINE B.T STUMP N53E 33.6'

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCC
Washburn Lake - BK#12 P. 16
at 5371' from E - offset 16' South to 2" I.P. w/
Cap 15/14
22/23

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____