Index No. N 21

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

NE 23 Corner common to sections 13, 14, 23, 24



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	BR. OAK	W. MAPLE	W. PINE	W. PINE
Diameter	12"	6"	30"	36"
Bearing	N18E	N55W	S62E	S48W
Distance	40 LKS	25 LKS	19 LKS	41 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK

Location filed COUNTY RESURVEY "E-10"

Monument IRON MONUMENT

1919, BEN CLARK, COUNTY BOOK "C" P. 337 FND PINE STUMP B.T. AND OAK 10" N16E 26.2' SET 3x30" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC

Washburn Lake - BK # 12 P. 14

at 5083' from E - offset 202.9' South to 2" I.P. Scribed ~~14/13~~ 13-28 also Fnd B. oak 14" S52"2W 58'

Bearing Trees, Reference Objects

Species	OAK			
Diameter	10"			
Bearing	S45W			
Distance	57.2'			

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____