Index No. N23

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

N1/4 24 Corner common to sections 13, 24



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	W. MAPLE	BR. OAK		
Diameter	7"	5"		
Bearing	NBE	SIOW		
Distance	12 LKS	26 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK

Location filed COUNTY RESURVEY "E-10"

Monument IRON MONUMENT

1919, BEN CLARK, COUNTY BOOK "C" P.323 SET 2½x48" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC

Washburn Lake - BK # 12 P.13

at 2640' from E - Set approx Corner

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____