


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. N3

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
N¹/₄ 19 Corner common to sections 18, 19



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>TAM</u>	<u>TAM</u>	_____
Diameter	<u>4"</u>	<u>6"</u>	_____
Bearing	<u>NRE</u>	<u>S78E</u>	_____
Distance	<u>13 LKS</u>	<u>7 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By BEN CLARK
Location filed COUNTY BOOK 'C' P. 326
Monument END TAM. POST 4" X 60" AND BITS:
6" TAM. STUMP S78E 9.44', 4" TAM NRE
9.4' SET IRON PIPE COUNTY RESURVEY - 1922
"E-11"

Evidence of Subsequent Corner Restoration

Year of search 1938 By CC
Washburn Lake - Bk # 12. P. 23
at 2640' from E - Set Approx '14 cor.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search Dec. 1924 By _____
Truport order shows NO SURVEY

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____