

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. N5

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 19 Corner common to sections 17, 18, 19, 20



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			Species
	<u>Y. PINE</u>	<u>Y. PINE</u>	<u>W. PINE</u>	
Diameter	<u>16"</u>	<u>18"</u>	<u>18"</u>	<u>Y. PINE</u>
Bearing	<u>N80E</u>	<u>N15W</u>	<u>S40E</u>	<u>S55W</u>
Distance	<u>16 LKS.</u>	<u>83 LKS</u>	<u>47 LKS</u>	<u>28 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1919 By BEN CLARK
Location filed COUNTY BOOK C¹ P. 333
Monument SET IRON PIPE PROPORTIONALLY
1922- COUNTY RESURVEY "E-71"

Evidence of Subsequent Corner Restoration

Year of search 1938 By CC
Washburn Lake - BK #12 P. 22
at 5280' from E - Set Approx loc.
1975 - Co Hwy Dept - Co RD # 49 2" i.p. in place

Bearing Trees, Reference Objects

Species	<u>N. PINE</u>	<u>J. PINE</u>	<u>N. PINE</u>
Diameter	<u>5"</u>	<u>10"</u>	<u>5"</u>
Bearing	<u>N76W</u>	<u>N60E</u>	<u>S35E</u>
Distance	<u>27.3'</u>	<u>40.7'</u>	<u>46.1'</u>

Bearing Trees, Reference Objects

Species	<u>N. Pine</u>	<u>N. Pine</u>
Diameter	<u>6"</u>	<u>20"</u>
Bearing	<u>NE</u>	<u>NW</u>
Distance	<u>87.0'</u>	<u>75.3'</u>
<u>1975 ties</u>		

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search Dec. 1926 By _____
Trwp rd order shows no survey
Dec. 1919, Trwp rd order shows no survey

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____