

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. N 9

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X NE 20 Corner common to sections 16, 17, 20, 21 Y _____



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1864
Original monument POST

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Distance
<u>ASPEN</u>	<u>ASPEN</u>	<u>W. BIRCH</u>	<u>ASPEN</u>
<u>7"</u>	<u>6"</u>	<u>7"</u>	<u>6"</u>
<u>N 29 E</u>	<u>S 33 E</u>	<u>S 53 W</u>	<u>N 07 1/2 W</u>
<u>17 LKS.</u>	<u>20 LKS</u>	<u>34 LKS</u>	<u>32 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1919 By BEN CLARK
 Location filed COUNTY BOOK C P. 313
 Monument F.W.O 1914 B.T.: 10" W. PINE N 6-30
102 LKS. SET 3' x 2 1/2' IRON POST IN SIDE OF RD
COUNTY RESURVEY 1922 'E-10, E-11' BEN CLARK

Year of search 1939 By CCC
Washburn Lake - BK# 12 R. 19
Start east from cc. in road

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Year of search Dec. 1926 By _____
Trap rd order shows no survey
May 1914; B.F. Clark
Trap rd order shows survey

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____