

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ by _____

Monument found _____

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed:

Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Location filed:

Monument:

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed:

Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____


Location filed:

Monument:

Index No. P13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 N. 5TH Coordinates: X _____ Y _____
E1/4 R1 Corner common to sections R1, 22



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1864
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing	Trees
<u>W. BIRCH</u>	<u>W. BIRCH</u>	
Diameter <u>12"</u>	<u>10"</u>	
Bearing <u>EAST</u>	<u>WEST</u>	
Distance <u>10 LKS</u>	<u>26 LKS</u>	

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1922 By BEN CLARK
 Location filed COUNTY RESURVEY "E-10"
 Monument Iron Monument
1919, BEN CLARK, COUNTY BOOK 8" P. 323 T.P.

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____