Index No. P21

# CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

E¼ 23 Corner common to sections 23, 24




O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1864

Original monument Post

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | R. OAK | R. OAK | | |
| Diameter | 8" | 7" | | |
| Bearing | 57 RE | 58 RW | | |
| Distance | 6 LKS | 13 LKS | | |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK

Location filed COUNTY RESURVEY "E-10"

Monument IRON MONUMENT

1919, BEN CLARK, COUNTY BOOK "C" P.323 FND I.P.

P 337 SET 2½x48" I.P.

### Evidence of Subsequent Corner Restoration

Year of search Apr 1998 By CC Land Dept. - J.L.A.R.

EXC condition

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____