


Index No. R 11

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
N 14 28 Corner common to sections 21, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species W. BIRCH ASPEN
Diameter 8" 10"
Bearing N63E S30W
Distance 50 LKS 31 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK
Location filed COUNTY RESURVEY "E-10, E-12"
Monument 1919, BEN CLARK, COUNTY BOOK "C" P. 315 SET Hua
P. 323. FWD I. P.
P. 336 SET 2 1/2 x 48" I. P. IN CENTER OF ROAD

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCC
Washburn Lake - BK# 13 P. 31
at 2640' from west - set approx cor 2" Aspen

Bearing Trees, Reference Objects

Species POPULAR
Diameter 9"
Bearing N35W
Distance 62.7'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____