Index No. R 21

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

NE26 Corner common to sections 23, 24, 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	W. PINE	R. OAK	ASPEN	W. MARLE
Diameter	20"	7"	8"	4"
Bearing	N68E	N51W	S48E	S18W
Distance	66 LKS	26 LKS	18 LKS	20 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK

Location filed COUNTY RESURVEY "E-10, E-11"

Monument IRON MONUMENT

1919, BEN CLARK, COUNTY BOOK "C" P.312 SET 3x30" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC

Washburn Lake - BK #13 P.26

at 5280' from E - Set approx Cor 3" Birch

Bearing Trees, Reference Objects

Species	W. BIRCH	POPLAR	PINE STUMP
Diameter	4"	6"	18"
Bearing	N2BW	N77E	S56-30E
Distance	37.3'	38.9'	45.5'

Bearing Trees, Reference Objects

R-21

Subsequent Corner Restoration

Year surveyed 3/03 By CCSO

Location filed #2003.013

Monument 2 1/4" ODIP, flush, on E Co. Rd #160. GPS, witness:

10" Maple N68°W, 53.52 *

8" Ash N56°E, 51.55 *

8" Maple S32°E, 36.03' *

20" R. Oak S15°W, 46.03' *

*distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____