Index No. R3

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

N 1/4 30 Corner common to sections 19, 30



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees			
Species	ASPEN	ASPEN	
Diameter	6"	6"	
Bearing	S80E	N85E	
Distance	190 LKS	175 LKS	

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK

Location filed COUNTY RESURVEY "E-11", "E-13"

Monument IRON MONUMENT

1918, BEN CLARK, COUNTY BOOK "C" P.299 FND BIRCH POST

" ✓ ✓ P.299, FND NE B.T. SET POST

1919 ✓ ✓ P309, 4x48" POPLAR POST

Bearing Trees, Reference Objects			
Species	POPLAR	POPLAR	
Diameter	4"	5"	
Bearing	N76 1/2W	S73E	
Distance	82.8'	20'	

Evidence of Subsequent Corner Restoration

Year of search 1919 By BEN CLARK

COUNTY BOOK "C" P.315 SET 2x48" I.P. FND GOV'T B.T: DOWN 6" POPLAR N8RE 175 LKS.

1939 - CCC - Washburn Lake - BK# 13 P.35, at 2480' from east - Fnd 1½" I.P. up 1½'

Bearing Trees, Reference Objects			
POPLAR	POPLAR		
5"	4"		
S24E	N14W		
27.7'	82.8'		

1919 TIES

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____