


Index No. T5

CASS COUNTY LAND CORNER RECORD

T. 139 R. 36 M. 5TH Coordinates: X _____ Y _____

E 1/4 30 Corner common to sections 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>ASPEN</u>	<u>Y. PINE</u>	_____
Diameter	<u>6"</u>	<u>10"</u>	_____
Bearing	<u>S70E</u>	<u>N75W</u>	_____
Distance	<u>25 LKS</u>	<u>13 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK
 Location filed COUNTY RESURVEY "E-12, E-13"
 Monument IRON MONUMENT
1918, BEN CLARK, BOOK "C" P. 297 FND A POST & B.T.
STUMP 10" Y. PINE N75W 13 LKS SET 4x36" POST
1919, BEN CLARK, BOOK "E" P. 315 SET I.P.

Evidence of Subsequent Corner Restoration

Year of search 3/2001 By CCSO
Found 1/4" Rebar, down 0.6', 3' W.
& CR #48. Probably set by PLS 21067
in 1991.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>
<u>10"</u>	<u>10"</u>	<u>12"</u>
<u>N55°W</u>	<u>S54°W</u>	<u>S86°E</u>
<u>82.46'</u>	<u>81.16'</u>	<u>57.91'</u>
<u>16d nail</u>	<u>16d nail</u>	<u>dbl. hd nail</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search May 1914 By B. F. Clark
Trwp rd order shows survey

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____