


Index No. V 15

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
N 1/4 34 Corner common to sections 27, 34



○ = Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1869
Original monument POST

Year of search _____ By _____
Monument found _____

Bearing Trees
Species W. BIRCH ASPEN _____
Diameter 6" 7" _____
Bearing S 24 W N 15 E _____
Distance 19 LKS 16 LKS _____

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK
Location filed COUNTY RESURVEY 'E-12"
Monument IRON MONUMENT
1919, BEN CLARK, COUNTY BOOK 'C' P. 316 FND POST
J. Pine 547E 17.5', 5' Poplar N 70W 28.8' Set 2 1/2 x 4 1/2" I.P.
P 339 FND BITS: 7"

Year of search 1939 By CCC
Washburn Lake - BL # 12 P. 29
at 2527' from E - Fnd 2" I.P. i B.T.S!
6" J. Pine 554E 17.9' 8" Aspen N 27E 25'

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____