Index No. V 21

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

NE 35 Corner common to sections 25, 26, 35, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees			
Species	W. PINE	W. PINE	W. PINE
Diameter	8"	10"	10"
Bearing	N78E	S80E	S40W
Distance	337 LKS	169 LKS	65 LKS

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK

Location filed COUNTY RESURVEY E-11

Monument IRON MONUMENT

1919, BEN CLARK, COUNTY BOOK "E" P.308 SET CORNER

✓ ✓ ✓ P339 TWO POST & BTS: POPLAR

9" N9E 86', 7" POPLAR S70W 70' SET PIPE

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCC

Washburn Lake - BK #12 P.26

at 5280' from E. set approx Cor.

1940 - BK #16 P2 at 2638' from N'4 36

Fn 1 I.P. 46' North - in Swamp.

Bearing Trees, Reference Objects

Species			
Diameter			
Bearing			
Distance			

Bearing Trees, Reference Objects

V-21

Subsequent Corner Restoration

Year surveyed 3/03 By CCSO

Location filed #2003.013

Monument 2" ODIP w/plumber cap, up 0.4', in swamp at S. end of Lake. GPS, and witness.

12" R. Oak S70°W 145.45 *

6" R. Oak S25°E 107.79 *

*distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____