Index No. V 23

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

N1/4 36 Corner common to sections 25, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	Aspen	W. Birch		
Diameter	9"	7"		
Bearing	N37E	S55E		
Distance	19 LKS.	51 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1922 By Ben Clark

Location filed County Resurvey "E-11"

Monument Iron Monument

1919, Ben Clark, Book "C" P.316 Fnd Post

P.339 Fnd Hub, Set 2 1/2x48" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCC

Washburn Lake - BK#12 P.25

at 2740' from E. Fnd 2" I.P. 28' N. of line

1940 - CCC - BK#16 P.1 at 2638.8' from east

tied into Iron pipe

BK#16 P.6 - at 2641' North of C1/4 - to P 4.3' west

Bearing Trees, Reference Objects

Species	Basswood	Basswood		
Diameter	8"	11"		
Bearing	S28E	N55W		
Distance	30.2'	56.8'		

Bearing Trees, Reference Objects

V-23

Subsequent Corner Restoration

Year surveyed 3/03 By CCSO

Location filed #2003.013

Monument 2" ODIP, run over by skidder, badly bent, spin for vertical. GPS and witness.

8" Maple N56°W, 41.39' *

6" Spruce N40°E, 84.15' *

6" Rt. Pine S9°W, 118.85' *

* distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____