


T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 36 Corner common to sections 25, 36 AND 30, 31-139-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

		Bearing Trees			
Species		ASPEN	ASPEN	ASPEN	ASPEN
Diameter		9"	14"	8"	12"
Bearing		N54E	S46E	S55W	N60W
Distance		14 LKS	17 LKS	31 LKS	20 LKS.

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK
Location filed COUNTY RESURVEY "E-11"
Monument
1919, SET 3x36" Poplar Post, BEN CLARK, BOOK "C" P. 307
1919, BEN CLARK, COUNTY BOOK "C" P. 314 SET 3x30" 1/2

Evidence of Subsequent Corner Restoration

Year of search March 1937 By CCC - Luke Washburn
Find 2" I.P. in place marked 25/30
36/31
BK#1 79.18 CH. from S
BK#2 P. 2 at 77 CH. from cast 8.37 CH. S. of Cor.

Bearing Trees, Reference Objects

Species W. PINE STUMP
Diameter 34"
Bearing S18E
Distance 5.7'

Bearing Trees, Reference Objects

Pine Stump
S30E Road 2.5 CH
14 LKS W. of Cor

Subsequent Corner Restoration

Year surveyed 1939 By CCC
Location filed Washburn Lake - BK#12 P. 25
Monument Start west from I.P.
1940 - CCC - BK#16 P. 1 Start west from I.P.
1940 - BK#16 P. 4 at 2640' from Elk Find I.P.
28.5' west
BK#20 - Corner 148' east of old grade

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____