


Index No. V 5

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 31 Corner common to sections 29, 30, 31, 32



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	W. PINE	Y. PINE	W. PINE	Y. PINE
Diameter	<u>22"</u>	<u>20"</u>	<u>24"</u>	<u>24"</u>
Bearing	<u>N10E</u>	<u>N85W</u>	<u>S80E</u>	<u>S70W</u>
Distance	<u>19 LKS</u>	<u>38 LKS</u>	<u>20 LKS</u>	<u>50 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK  
Location filed COUNTY RESURVEY "E-12, E-13, E-14"  
Monument IRON MONUMENT  
1918, Ben Clark Book C' P 298 SET HUB  
1919 ✓ P 315 SET 3X30" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1939 By CC  
Washburn Lake - BK # 12 P. 33  
Set east from cor.  
BK # 12 P. 36 at 4960' from W. Corner in center of road

Bearing Trees, Reference Objects

Species	Bearing Trees, Reference Objects		
	POPLAR	POPLAR	POPLAR
Diameter	<u>6"</u>	<u>6"</u>	<u>5"</u>
Bearing	<u>S18E</u>	<u>S37W</u>	<u>N25E</u>
Distance	<u>43'</u>	<u>47.3'</u>	<u>41'</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search May 1914 By B.F. Clark  
Trwp rd order shows survey

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_