


Index No. V 9

CASS COUNTY LAND CORNER RECORD



T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 32 Corner common to sections 28, 29, 32, 33

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1864
 Original monument POST

Species	Bearing	Tree	Distance
<u>ASPEN</u>	<u>ASPN</u>	<u>FIR</u>	<u>ASPEN</u>
<u>12"</u>	<u>11"</u>	<u>11"</u>	<u>10"</u>
<u>N40E</u>	<u>S48E</u>	<u>S41W</u>	<u>N50W</u>
<u>17 LKS</u>	<u>9 LKS</u>	<u>29 LKS</u>	<u>10 LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

○ = Corner

Subsequent Corner Restoration
 Year surveyed 1922 By BEN CLARK
 Location filed COUNTY RESURVEY 'E-12, E-14"
 Monument IRON MONUMENT
1918, BEN CLARK, COUNTY BOOK 12 P. 304 5" x 3/8" POPLAR POST
1919 ✓ P. 336 F.W. POST: 1918 B.T.S
SET I.P. W/ CAR

Evidence of Subsequent Corner Restoration
 Year of search 1939 By CCC
Washburn Lake - BK # 12 P. 31
start east from corner.
BK 12 P. 34 - at 5280' from W. - set approx cor.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>POPLAR</u>	<u>7"</u>	<u>S51W</u>	<u>28.9'</u>
<u>POPLAR</u>	<u>6"</u>	<u>S22E</u>	<u>36.2'</u>
	<u>1918</u>	<u>B.T.S</u>	

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____