


T. 139 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
SE 34 Corner common to sections 34, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees	Distance
<u>SOFT MAPLE</u>	<u>OAK</u>	<u>W. BIRCH</u>	<u>BL. OAK</u>
<u>5"</u>	<u>5"</u>	<u>6"</u>	<u>15"</u>
<u>N57E</u>	<u>S46W</u>	<u>S7W</u>	<u>N83W</u>
<u>26 LKS</u>	<u>39 LKS</u>	<u>14 LKS</u>	<u>5 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK  
Location filed COUNTY RESURVEY "E-11, E-12"  
Monument 1918, BEN CLARK, COUNTY BOOK "C" P. 296 SET 4x36" POPLAR POST ON AN OPEN HILL.

Evidence of Subsequent Corner Restoration

Year of search 1919 By BEN CLARK  
COUNTY BOOK "C" P. 338 FND GALT B.T.S BIRCH 8" N65E 3', 10" POPLAR S70E 8 LKS AND 2 OTHER STUMPS THAT FRT AND ALSO POPLAR POST SET 3x30" 1.P.  
1939- CCC - Washburn Lake - BK#13 P. 40 at 52.30' from E-2" 1.P. 52.52' from W. P. 50

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_