


T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
S1/4 36 Corner common to sections 36



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1863
 Original monument POST

Bearing Trees

Species	<u>W. BIRCH</u>	<u>W. BIRCH</u>	_____	_____
Diameter	<u>6"</u>	<u>6"</u>	_____	_____
Bearing	<u>N9W</u>	<u>S18W</u>	_____	_____
Distance	<u>31KS</u>	<u>30KS</u>	_____	_____

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 1922 By BEN CLARK
 Location filed COUNTY RESURVEY "E-11"
 Monument 1 Row MONUMENT
1919, BEN CLARK, COUNTY BOOK "C" P314-315 SET 2x48" I.P.

Evidence of Subsequent Corner Restoration
 Year of search 1939 By CCC
Washburn Lake - BK # 13 P. 37
at 2670' from E - End 2" I.P. up 3' 40' N of line
also End 6" I.P. 16" N. line N47 1/2 E 34'
1940 - BK # 16 P. 5 at 2659' from SE 36 End I.P.
40' North

Bearing Trees, Reference Objects

Species	<u>N. PINE</u>	<u>Ironwood</u>	_____	_____
Diameter	<u>13"</u>	<u>4"</u>	_____	_____
Bearing	<u>N49E</u>	<u>S45W</u>	_____	_____
Distance	<u>33.2'</u>	<u>46.9'</u>	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____