


Index No. A 12-13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 29 M. 5TH Coordinates: X _____ Y _____
MC # 59 Corner common to sections 4 AND 33 - 140-29



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species ASPEN ASPEN _____
Diameter 5" 5" _____
Bearing S15E N50E _____
Distance 19 LKS 13 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLATS -
BIRCH PARK
John Howard - 1957 - (was not labeled)
WC
Certificate - Landecker - 1984 Doc # 276691
Find 2" i.p. up 0.4' Set 2x2x36" metal
post w/cup UP 0.9'
Br. oak 9" N45E 17.54'
Br. oak 8" East 37.50'
Poplar 8" S25E 25.25'
Br. oak 8" S10W 33.60'

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____