Index No. J 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 29 M. 5TH Coordinates: X _____ Y _____

NE 13 Corner common to sections 12, 13 AND 7, 18-139-28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	ASPEN	TAM	WILLOW	TAM.
Diameter	12"	10"	6"	11"
Bearing	N32E	S69E	S35W	N50W
Distance	27 LKS	44 LKS	39 LKS	32 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1911 By JOHN CURO

Location filed COUNTY SURVEY RECORD BOOK "A" P364-368

Monument FND ORIG. STAKE AND ROOTS OF OLD GOVT. B.T.S

1922 - COUNTY RESURVEY "E-9, E-11" BEN CLARK I.M.

1919, BEN CLARK COUNTY BOOK "C" P.327 FND OAK POST

P. 333. SET 2 1/2 x 36" W.P.

Evidence of Subsequent Corner Restoration

Year of search 1911 By GLO -

FND ORIG POST - B.T.S ARE DESTROYED BY FIRE

1938 - CCC - Washburn Lake - BK # 13 P.24

at 5260' from E - corner in Lake

1911 - also on microfilm - roll 115 BK 73 P.37

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 3/9/88 By Donn Rasmussen

Location filed Cert. Filed Doc. # 3046061

Monument Found 2 1/2" x 36" capped iron pipe

TBS: 6" Aspen N18W 61.51'; 4" Ash N80E 37.65'; 8" Ash S40E 51.66'; 12" Twin Ash S50W 73.76'.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____