


T. 139 R. 29 M. 5TH Coordinates: X _____ Y _____
n 14 20 Corner common to sections 17, 20



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument POST

Species	Bearing	Trees
<u>N. PINE</u>	<u>N. PINE</u>	
Diameter <u>18"</u>	<u>24"</u>	
Bearing <u>N 20 1/2 E</u>	<u>S 3 E</u>	
Distance <u>90 LKS</u>	<u>72 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1927 By _____

Location filed _____

Monument Co DITCH SURVEY BK 160 BOX 3 OF
Co DITCH SURVEY BOOKS, PG 2

Evidence of Subsequent Corner Restoration

Year of search 7/01 By CCSO

Found R/R spike, flush, on E Hwy #87,
11'E. of Cormorant Lane.

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

W. Oak	Spruce	W. Pine
<u>8"</u>	<u>12"</u>	<u>8"</u>
<u>N 26° W</u>	<u>N 38° E</u>	<u>S 52° E</u>
<u>66.27'*</u>	<u>62.25'*</u>	<u>67.54'*</u>

*distance to double head nail

N-7

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument MARCH 2005 J. Leas # 42619
Cert. of Survey shows monument found.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

APR 2002 D. LANDECKER
CERT OF SURV SHOWS MON FOUND

OCT. 2003 J. Leas # 42619
Cert. of SUR. Shows mon. set