


T. 139 R. 29 M. 5th Coordinates: X _____ Y _____

MC #6 Corner common to sections 21,22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>W. Pine</u>	<u>N. Pine</u>	_____	_____
Diameter	<u>20"</u>	<u>20"</u>	_____	_____
Bearing	<u>N 66° E</u>	<u>N 59° W</u>	_____	_____
Distance	<u>38 links</u>	<u>73 links</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 7/1987 By STEVENSON & ASSOCIATES
Location filed: Curo file 1957
Monument: Found 1.5" pipe, 1369.88 south of East 1/4 corner of Sec. 21. Old stumps intersect 17.42' S 10° E of found pipe.

Evidence of Subsequent Corner Restoration

Year of search 8/2019 By J. Kramer, LS 23668
Location filed: Certificate of Location
Monument: Found 1.5" iron pipe on old fence line, 30'+/-, to Lake Ada and witnessed as follows, trees have a nail/disc in base.

Bearing Trees, Reference Objects

Species	<u>Pine</u>	<u>Oak</u>	<u>J. Pine</u>	<u>J. Pine</u>
Diameter	<u>stump</u>	<u>8"</u>	_____	<u>6"</u>
Bearing	<u>N 50° W</u>	<u>N W</u>	<u>N E</u>	<u>S W</u>
Distance	<u>33.4' (GLO?)</u>	<u>21.15'</u>	<u>20.97'</u>	<u>3.72'</u>

Bearing Trees, Reference Objects

Species	<u>Red Oak</u>	<u>Red Oak</u>	<u>White Pine</u>	_____
Diameter	<u>9"</u>	<u>16"</u>	<u>24"</u>	_____
Bearing	<u>N 55° W</u>	<u>N 18° E</u>	<u>S 82° E</u>	_____
Distance	<u>4.02'</u>	<u>21.20'</u>	<u>19.53'</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

