


Index No. V 15

CASS COUNTY LAND CORNER RECORD

T. 139 R. 29 M. 5TH Coordinates: X _____ Y _____
N¹⁴ 34 Corner common to sections 27, 34 W.C.



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post W.C. 22.68 CH. EAST

Bearing Trees	
Species <u>N. Pine</u>	<u>AL. Pine</u>
Diameter <u>4"</u>	<u>10"</u>
Bearing <u>S 22 E</u>	<u>N 15 E</u>
Distance <u>4 LKS</u>	<u>500 LKS.</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed Dec 2002 By CCSO
Location filed _____
Monument W.C. N¹⁴
Found 2" ODIP, up 1.8; 4'± from edge of marsh, 92± from open water.

Evidence of Subsequent Corner Restoration

Year of search 7/1921 By E.B. Horst
Roll 12, BK 166, pg 44, set wood post from N.P. BT.

Bearing Trees, Reference Objects

Species <u>N. Pine</u>	<u>J. Pine</u>	<u>W. Oak</u>
Diameter <u>12"</u>	<u>10"</u>	<u>6"</u>
Bearing <u>N 64° E</u>	<u>S 30° E</u>	<u>S 68° W</u>
Distance <u>17.40*</u>	<u>33.42*</u>	<u>4.68*</u>

* Dist. to dbl head nail.

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

V-15

Subsequent Corner Restoration

Year surveyed April 1947 By J. Curo
Location filed Roll 15, BK 247, Pg 89
Monument Found 1M pipe 60' East of water.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____