


Index No. X 13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 33 Corner common to sections 33, 34



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>TAM.</u>	<u>TAM.</u>	_____
Diameter	<u>4"</u>	<u>4"</u>	_____
Bearing	<u>S33W</u>	<u>S72E</u>	_____
Distance	<u>12 LKS</u>	<u>11 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By E. B. HORST
Location filed COUNTY BOOK 2 P 350
Monument FRG POST SET BY CURO

Evidence of Subsequent Corner Restoration

Year of search Dec. 1917 By _____
Twp rd order shows no survey

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

(X-13)

Subsequent Corner Restoration

Year surveyed 3/1918 By H. Curo
Location filed Roll 13, BK 202, pg 26 & 38
Monument No original evidence, set 2"x2"x36" in Tam bog, no BT'S.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

7/2005 - CC 50 - # 2000.048, Set 1 1/2" ODIP, down 0.3', 3'± W. of G. Co. Rd. #43.

<u>4" Tamarack</u>	<u>S64°W</u>	<u>52.94'*</u>
<u>P. Pole</u>	<u>S85°E</u>	<u>35.22'*</u>
<u>12" J. Pine</u>	<u>S20°E</u>	<u>159.24'*</u>

*distance to double head nail

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____