


Index No. A 11

CASS COUNTY LAND CORNER RECORD

T. 139 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1/4 4 Corner common to sections 4 and 33-140-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>BL. PINE</u>	<u>BL. PINE</u>
Diameter <u>5"</u>	<u>5"</u>
Bearing <u>N19W</u>	<u>SRE</u>
Distance <u>15 LKS</u>	<u>50 LKS</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1911 By HARRY S. TODD  
Location filed COUNTY SURVEY RECORD BOOK A P373-377  
Monument FIND IRON SET BY CURD SET 2X 48" CAPPED GALV. I.P.

Evidence of Subsequent Corner Restoration

Year of search 1972 By CO HWY DEPT  
CO RD # 45  
2" capped I.P.

Bearing Trees, Reference Objects

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Bearing Trees, Reference Objects

<u>P.P.</u>	<u>N 1/2 line</u>	<u>N 1/2 line</u>
	<u>3"</u>	<u>3"</u>
<u>SSW</u>	<u>SSE</u>	<u>SE</u>
<u>118.6'</u>	<u>81.1'</u>	<u>76.8'</u>

A-11

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By CCSO  
P.K. impl. set from CCHD ties. located  
& CSAH 45 + & co. rd. 117 flush w/ bit.

REF. TIES:

<u>P. Pole</u>	<u>N 32° W</u>	<u>55.18'</u>
<u>P. Pole</u>	<u>N 80° E</u>	<u>243.32'</u>
<u>11" R. Pine</u>	<u>S 50° E</u>	<u>76.30'</u>
<u>P. Pole</u>	<u>S 10° W</u>	<u>117.23'</u>

Corner GPS CCSO 7/23/02  
CCSO fd PK on & &

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_