


Index No. A15

CASS COUNTY LAND CORNER RECORD

T. 139 R. 30 M. 5TH Coordinates: X _____ Y _____
N/4 3 Corner common to sections 3 AND 34-140-30



EXISTING SURVEYS

Original Government Survey
Year surveyed 1865
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species W. PINE N. PINE
Diameter 14" 18"
Bearing S47E N16W
Distance 95 LKS 22 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1972 By Co Hwy Dept.
Location filed Co Rd #45
Monument 2" I.P. in place
P.L. old roads

Evidence of Subsequent Corner Restoration
Year of search 1969 By R.F. Schneider
Found 2" iron pipe at road intersection

Bearing Trees, Reference Objects
Species Oak W. oak
Diameter TWIN 4" TWIN 6"
Bearing NE E
Distance 71.8' 46.5'

Bearing Trees, Reference Objects
W. Oak R. Oak
6" 8"
S9°W N49°W
46.38' 139.40'

A-15

Subsequent Corner Restoration

Year surveyed 4/03 By Landecker & Assoc
Location filed _____
Monument Found 1" pin, down 9" and
1969 witness tree. A C of L was
filed.

12" Twin Oak S9°W, 46.42' (1969)
9" R. Oak S36°E, 61.40'

Evidence of Subsequent Corner Restoration Found

Year of search July 2005 By J. Freeman #21367
Cert. of Survey shows monument found

Remonumentation certificate prepared Doc. No. 465973
Filed at CCRO

By #21367
Date 5/1/03