

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 139 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 15 Corner common to sections 10, 11, 14, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees			
Species	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>
Diameter	<u>12"</u>	<u>12"</u>	<u>6"</u>
Bearing	<u>N67E</u>	<u>N37W</u>	<u>S48 1/2 W</u>
Distance	<u>33 LKS</u>	<u>9 LKS</u>	<u>29 LKS</u>

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURD
Location filed COUNTY RESURVEY "E-34"
Monument 2 1/4 x 4 1/8" IRON MONUMENT
1915, F.A. DANNER, BOOK "O" P. 40 FND NW 1/4 SW B. 15 AND
NE B. T (DOWN) SET 80d SPIKE P. 43, SET I.M. AND
DIG PITS: MAKE MOUND AROUND PIPE

Evidence of Subsequent Corner Restoration

Year of search 1970 By DNR
Map's notes in file
Found 1 1/2" capped pipe

Bearing Trees, Reference Objects

Species - also on microfilm - roll 115 BK 79 P. 45
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Birch	Poplar	Poplar
8"	10"	12"
SW	SE	NE
6.6'	18.8'	24.4'

Subsequent Corner Restoration

Year surveyed 1987 By Dave Landecker
Location filed Doc # 298534
Monument Fnd 2" I.P. w/ 3" Cap.
11" Poplar S68°W 24.84'
6" Birch S10°E 48.29'
11" Poplar S62°E 19.27'
11" Poplar N80°E 29.26'
10" Poplar N25°E 24.79'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - LUDY BAY
JOHN M. GREENE 1925
Certificate - Dave Landecker - 1987