


T. 139 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 18 Corner common to sections 7, 8, 17, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	N. PINE	N. PINE	N. PINE	N. PINE
Diameter	10"	12"	12"	12"
Bearing	N19E	N58W	S25E	S68W
Distance	8 LKS	22 LKS	15 LKS	21 LKS

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1907 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK A P 138-139
Monument END 10" N. PINE N19E 5.3', 12" N. PINE N58W 14.5', 12" N. PINE N25E 9.9', 12" N. PINE S68W 13.9'
SET 8x8x36" CONCRETE POST

Evidence of Subsequent Corner Restoration

Year of search 1941 By JOHN CURO
COUNTY BOOK D P 260-261 END 8x8x36" CONCRETE MON.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

POPULAR	J. PINE	WITNESS PINE	WITNESS PINE	N. PINE	J. PINE
6"	8"	2"	2"	5"	12"
N43-50E	N69-17E	S45E	S45W	N42-23W	N18-35W
49.00'	109.3'	43.0'	55'	51.25'	63.10'

Subsequent Corner Restoration

Year surveyed 1924 By Miss Hux Foot
Location filed PLW map in Recorder's office
Monument Lethrop to Pine River
Concrete monument

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - R.F. SCHNEIDER - 1967
Set Cass County cast iron monument, TIES:
1 1/2" iron bar SE 42.94'; 12" Norway Pine NW
50.75'; guy pole NE 17.69'; TELE. pole
SSE 25.27'

Jul 2002 - Found cym down O. 7,
2' ± N. of Driveway, 52' ± E. of
Driveway.

8" W. Pine	S15°E	26.34' *
16" W. Pine	S10°W	47.79' *
P. pole	N58°W	43.26' to 8d nail

* - Dist. to dbl hd nail