


Index No. L 17

CASS COUNTY LAND CORNER RECORD

T. 139 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 14 15 Corner common to sections 14, 15



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species ASPEN  
Diameter 5"  
Bearing S85W  
Distance 50LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURO  
Location filed COUNTY RESURVEY "E-34"  
Monument 2 1/4 x 48" IRON MONUMENT  
1915, GORMAN, BOOK D' P. 41 SET CORNER P. 45 SET  
2 1/4 x 48" I.M.  
also on microfilm roll 115 BK79 P. 101

Evidence of Subsequent Corner Restoration

Year of search 1970 By DNR  
Maps & notes in file  
End 1 1/2" capped pipe

Bearing Trees, Reference Objects

Species set I.M. - dig pits N&S 6"  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

N. line	Paple	Paple	Paple	oak	Paple
16"	10"	6"	12"	3"	8"
SE	WSW	NW	NNW	NNE	SSW
20.7'	14.6'	14.1'	16.7'	13.1'	15.3'

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_