


Index No. N 18-19

CASS COUNTY LAND CORNER RECORD

T. 139 R. 30 M. 5TH Coordinates: X _____ Y _____
MC# 8 Corner common to sections 14, 23



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>LINDEN</u>	<u>LINDEN</u>	_____
Diameter	<u>5"</u>	<u>6"</u>	_____
Bearing	<u>S76W</u>	<u>N16 1/4 W</u>	_____
Distance	<u>13 LKS</u>	<u>25 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURRO
 Location filed COUNTY RESURVEY "E-34"
 Monument 2 1/4 x 48" IRON MONUMENT AND GUIT BOLTS
1915, GORMAN, BOOK "D" P. 40 SET BASSWOOD STAKE
P. 44 SET 2 1/2 x 48" CAPPED I.M.
also on micro film - roll 115BK79 P. 57

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>1.98 set I.M. - dig pit 6' w.</u>	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Plat - Portage View - Walt Curro - 1983

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____