


Index No. R 19-20

CASS COUNTY LAND CORNER RECORD

T. 139 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 16 Corner common to sections 23, 26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>BL. PINE</u>	<u>BL. PINE</u>	_____
Diameter	<u>8"</u>	<u>10"</u>	_____
Bearing	<u>S57 3/4 E</u>	<u>N61 W</u>	_____
Distance	<u>34 LKS</u>	<u>14 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1941 By JOHN CURO  
Location filed COUNTY BOOK 'D' P 262-263.  
Monument 2" PIPE FOR U.S.M.C.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - NORTHERN ESTATES  
HAROLD CURO 1959

Nov 2002 D. JOHNSON # 11752  
Survey shows mon. found

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_