


Index No. A 1

CASS COUNTY LAND CORNER RECORD

T. 139 R. 31 M. 5TH Coordinates: X _____ Y _____
NW 6 Corner common to sections 6 AND 31-140-31

O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	<u>Pine</u>	<u>Pine</u>	<u>PINE</u>	<u>PINE</u>
Diameter	<u>10"</u>	<u>10"</u>	<u>12"</u>	<u>12"</u>
Bearing	<u>N52W</u>	<u>S64W</u>	<u>S50E</u>	<u>N45E</u>
Distance	<u>58 LKS</u>	<u>65 LKS</u>	<u>98 LKS</u>	<u>12 LKS</u>

Species	Original Bearing Trees Found			
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1913 By John Curo
Location filed microfilm - roll 115 BK 85 P. 313-318
Monument running lines for corner
1921 - EB. 1st BK 85 P 317 set 2x4x8" l.m.

Evidence of Subsequent Corner Restoration

Year of search Aug. 2000 By CCSO
Fnd. in place; CIM down 0.5'. Located
6' E of C.R. #41, 4' E of Rd to West, and 40' ± S
of 4 Driveway east.

Bearing Trees, Reference Objects

Species			
Diameter			
Bearing			
Distance			

Bearing Trees, Reference Objects

J. Pine	J. Pine	P. Pole	J. Pine
<u>8"</u>	<u>9"</u>		<u>6"</u>
<u>N 72° W</u>	<u>S 71° E</u>	<u>S 23° E</u>	<u>S 61° W</u>
<u>52.30'</u>	<u>65.22'</u>	<u>105.87'</u>	<u>55.39'</u>
<u>(exist tag B.T.)</u>			<u>(exist tag BT)</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument Corner GPS CCSO 7/25/02
CCSO Fd. CIM, down 0.4, 6' ± E. of 4
ce. Rd #41, on 4 160th st.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remuneration certificate prepared _____

By _____

Filed at _____

Date _____