


Index No. N 9

CASS COUNTY LAND CORNER RECORD

T. 139 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 20 Corner common to sections 16, 17, 20, 21



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing Trees			
	TAM.	TAM.	W. LINE	ASPEN
Species	<u>TAM.</u>	<u>TAM.</u>	<u>W. LINE</u>	<u>ASPEN</u>
Diameter	<u>6"</u>	<u>8"</u>	<u>7"</u>	<u>7"</u>
Bearing	<u>N60W</u>	<u>S88E</u>	<u>S22 3/4 E</u>	<u>S31 1/4 W</u>
Distance	<u>7 LKS.</u>	<u>56 LKS</u>	<u>79 LKS</u>	<u>29 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1911 By JOHN CLAR  
Location filed COUNTY SURVEY RECORD BOOK 'A' P 313-317  
Monument SET HUB FROM OLD GANT BIT STUMP  
1915, CLARK, BOOK 'D' P. 11 FND. NEW BIT AND REMAINS OF  
OTHER BITS SET CORNER.  
also on microfilm - roll 105 BK 64 P. 6, P. 15-set in.

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1990 ± By L. OLSON, LAND DEPT  
FOUNDA MONUMENT

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_