

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R5

CASS COUNTY LAND CORNER RECORD

T. 139 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 30 Corner common to sections 19, 20, 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	
<u>N. PINE</u>	<u>BL PINE</u>	<u>N. PINE</u>	<u>N. PINE</u>
Diameter <u>15"</u>	<u>16"</u>	<u>16"</u>	<u>13"</u>
Bearing <u>N66 1/2 E</u>	<u>S14 W</u>	<u>N84 1/2 E</u>	<u>N80 1/2 W</u>
Distance <u>98 LKS</u>	<u>84 LKS</u>	<u>111 LKS</u>	<u>121 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1908 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK "A" P. 313-317
Monument SET HUB FROM ORLG P. 15' 16" J. PINE S14W 55.4'
16" N. PINE N84-15E 73.3'
In 1911 SET 2x98" I.P. IN CONCRETE
1915, SCOTT, BOOK "D" P. 11 TND I.M.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
← also on microfilm - roll 115 BK 85 P. 173, 308

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

R-5

Subsequent Corner Restoration

Year surveyed Sept. 1905 By W.H. Hallett
Location filed Road orders & Trip file
Monument Road order list corner
1600 chs south of lake and
witnesses as follows:
N. Pine N66 1/2 E 22
B. Pine S14 W 52
N. Pine N84 1/4 E 75
N. Pine N80 1/2 W 61

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____