


Index No. A 17

CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 3 Corner common to sections 2, 3



EXISTING SURVEYS

Original Government Survey

Year surveyed 1867  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>FIR</u>	<u>Bl. Ash</u>	_____	_____
Diameter	<u>4"</u>	<u>14"</u>	_____	_____
Bearing	<u>S34<sup>1</sup>/<sub>2</sub>E</u>	<u>S17<sup>1</sup>/<sub>2</sub>W</u>	_____	_____
Distance	<u>14LKS</u>	<u>17LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC  
Location filed Washburn Lake - BK # 4 P. 41  
Monument Start E. at approx corner

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_