R M Co				
Corner common to se	ctions			
	EX	STING SURVEYS		
Original Governmen	t Survey	Original Evidence F	ound	
Year surveyed		Year of search	by	
Original monument		Monument found		
				= Corne
Bearing Tree	S		Original Bearing Tre	ees Found
Species				
			,	
Distance		Distance	,	
Subsequent Corner R	estoration	Evid	dence of Subsequent C	corner Restoration
Location filed:		Location filed:	``	
Monument:		Monument:		
	Reference Objects		Bearing Trees	s, Reference Objects
Species				
Diameter		Diameter Bearing	,	
Distanco		Distance	·	
Subsequent Corner R	estoration	Evidenc	ce of Subsequent Corne	er Restoration Found
Year surveyed By		Year of search	Ву	
Location filed:		Location filed:		
Monument:		Monument:		

Index No. <u>A ZI</u> CASS COUNTY LANE	- CORNER RECORD		
+ 140 p 25 4 5774 Constinution X	v		
T. <u>140</u> R. <u>25</u> M. <u>5774</u> Coordinates: X <u>NE R</u> Corner common to sections <u>42</u>			
Original Government Survey	SURVEYS Original Evidence Found		
Year surveyed 1867	Year of searchBy	+++	
Original monument Post	Monument found		
	۹ ۱	O = Corner	
Species W. ANE W. CEDAR	Original Bearing Trees Found	_	
Diameter 10" 12"	Diameter		
Bearing 547 3/4E 5431/2 W	Bearing		
Distonce <u>204ks</u> <u>304ks</u>	Distance		
Subsequent Corner Restoration	Evidence of Subsequent		
Year surveyed 1937 By CCC. Location filed Weghburn Luke - BK#4 0.41	Year of searchBy		
Manument Set approx car at 5280' From west			
Manument Set approx car at 5280' From west 1937-BK#5 BJ Start E. From APPRox Cor.			
		· · · · · · · · · · · · · · · · · · ·	
Beoring Trees, Reference Objects	Bearing Trees, Reference	e udjects	
Species			
Bearing			
Distance	······································	······································	
	U		
Subsequent Corner Restoration Year surveyed By Location filed Image: Subsequent Structure Monument Image: Subsequent Structure	Evidence of Subsequent Corn Year of search By		
Remonumentation certificate prepared	<u>R</u>		
Filed at	By Date		