

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. G 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 11 Corner common to sections 11, 12



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1867  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species SPRUCE ASPEN  
Diameter 6" 5"  
Bearing N46W N62E  
Distance 16 LKS 4 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1916 By E. B. HOEST  
Location filed COUNTY BOOK "C" P. 536  
Monument TWP. AND GLO NOTES CALL FOR: 8" OAK  
N30W 52 LKS - END PLAINLY MARKED SET CORNER

Evidence of Subsequent Corner Restoration

Year of search 1931 By P. C. WARNER  
PIPE  
MAP ON FILE IN TWP FILE  
MAP FROM ITASCA CO. SURVEYOR.

also on microfilm - roll 1105 BK 68 P. 9

Bearing Trees, Reference Objects

Species OAK BALSAM  
Diameter 8" 8"  
Bearing N30W N34-30E  
Distance 34.3' 65.8'

Bearing Trees, Reference Objects

POPULAR MAPLE  
6" 7"  
56.7E N80W  
59.7' 79.6'

G-21

Subsequent Corner Restoration

Year surveyed 1905 By C. Taylor  
Location filed Twp. Road Orders  
Monument Surveyors Report indicates  
corner post.

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

1911, M. Watson Twp. Road Orders,  
Surveyors Report indicates road  
on E-W 1/4 line.

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_