Index No. J 5

# CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X _____ Y _____

NE 18 Corner common to sections 7, 8, 17, 18




O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1867

Original monument Post

### Original Evidence Found

Year of search _____ By _____

Monument found _____

| Bearing Trees | | | | |
|---|---|---|---|---|
| Species | Spruce | Spruce | Spruce | Spruce |
| Diameter | 4" | 10" | 4" | 5" |
| Bearing | N38W | N38E | S69W | S65½E |
| Distance | 9 LKS. | 12 LKS | 21 LKS | 7 LKS |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1937 By CCC

Location filed Wash Burn Lake - Bk # 2 P. 67

Monument at 5280' From east - Set approx Cor

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____