


Index No. N 17

CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X _____ Y _____
NE 22 Corner common to sections 14, 15, 22, 23



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1867
Original monument: Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	TAM.	TAM.	TAM.	TAM.
Diameter	6"	6"	6"	5"
Bearing	N55W	N29E	S40W	S27 1/2 E
Distance	22 LKS	17 LKS	21 LKS	16 LKS

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By E. B. Hest
Location filed County Book 'C' P. 535
Monument Find 1 TAM B.T. SET CORNER.

also on microfilm - roll 105 BK 68 P. 2, P. 29
on P. 29 set I.M.

Species	Bearing Trees, Reference Objects			
	DEAD TAM.	SPRUCE	DEAD TAM.	SPRUCE
Diameter	10"	8"	8"	5"
Bearing	N16W	N62E	S40W	S52E
Distance	6.4'	45.0'	14.0'	15.7'

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK #3 P. 20
at 5280 from east - set approx cor.

May 1923, Two rd order shows no survey

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____