Index No. N3

# CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X _____ Y _____

N1/4 19 Corner common to sections 18, 19




O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1867

Original monument Post

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | ASPEN | BIRCH | | |
| Diameter | 8" | 10" | | |
| Bearing | N77W | S76E | | |
| Distance | 15 LKS. | 26 LKS | | |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____