Index No. V 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X _____ Y _____

NE 35 Corner common to sections 25, 26, 35, 36



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1867

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	FIR	W. CEDAR	W. CEDAR	W. CEDAR
Diameter	8"	4"	8"	5"
Bearing	S85E	S56W	N54W	N59E
Distance	8 LKS	9 LKS	24 LKS	24 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1937 By CCC

Location filed Washburn Lake - BK #2 P.53

Monument at 2640 From east - Set 4" Post - Approx Cor.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____