


Index No. V 7

CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 14 32 Corner common to sections 29, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1867  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>TAM.</u>	<u>TAM.</u>	_____	_____
Diameter	<u>3"</u>	<u>3"</u>	_____	_____
Bearing	<u>S 76 E</u>	<u>N 56 1/2 W</u>	_____	_____
Distance	<u>30 LKS</u>	<u>8 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC  
Location filed Washburn Lake - BK # 2 P. 9  
Monument Set approx 1/4 post 40 CH. from west

Evidence of Subsequent Corner Restoration

Year of search May 1923 By \_\_\_\_\_  
Typed order shows no survey

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_