

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. B-C 17

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
MC# 2 Corner common to sections 2,3



EXISTING SURVEYS			
Original Government Survey		Original Evidence Found	
Year surveyed <u>1871</u>		Year of search _____	By _____
Original monument <u>Post</u>		Monument found _____	
Bearing Trees		Original Bearing Trees Found	
Species <u>SR. PINE</u>	<u>ALDER</u>	Species _____	_____
Diameter <u>10"</u>	<u>5"</u>	Diameter _____	_____
Bearing <u>S32E</u>	<u>S56W</u>	Bearing _____	_____
Distance <u>14 LKS.</u>	<u>21 LKS</u>	Distance _____	_____
Subsequent Corner Restoration		Evidence of Subsequent Corner Restoration	
Year surveyed _____	By _____	Year of search _____	By _____
Location filed _____			
Monument _____			
Bearing Trees, Reference Objects		Bearing Trees, Reference Objects	
Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed <u>1971</u>	Year of search _____
By <u>Don Coulter</u>	By _____
Location filed _____	
Monument <u>Ed. 1 1/2" iron pipe</u>	
Trees:	
<u>14" Ash NE 16.7</u>	
<u>12" Ash North 10.3</u>	
<u>12" Tw. Ash NW 5.0</u>	
<u>center of road south 30'±</u>	

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____