


Index No. C 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
E1/4 2 Corner common to sections 112



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species ASPEN BIRCH
Diameter 4" 10"
Bearing S51W S17E
Distance 70 LKS 205 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washington Lake - BK # 5 P. 3
Monument at 2404' from S. set APPROX 1/4 cor.
in middle of road.
1938 - at 2586' from South - corner under road -
B.T.S: 10" Elm N67°24'W 46.3', 14" W. oak S68°E 43.8'

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____